

SWM - 15" Dutch Creek Interceptor
Damage - Emergency Repair

192 OF VCP
392 OF VCP
C-28-16

Damaged Sewer
by Boring Machine

Approximately 85
Feet Needs
Replacement.

141 OF CPP

COAL MINE AVE

C-28-17

CW.1

CW.2

202 OF CPP

135 OF P.VC

VACAN

